

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/28/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 09/27/12 – 0700, 10/04/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, Illinois
8. Activity Log			
Time	Major Events		
1000	<ul style="list-style-type: none"> Boat safety briefing at E4.0 boat launch. <p>Operational status:</p> <ul style="list-style-type: none"> Sheen ribbons observed at C0.4 boat launch. Sheen sweeper boat observed operating along LDB across from C0.4 boat launch. MP5.75 LDB, spontaneous sheen observed just downstream from trestle. Ceresco Dam, spontaneous sheen observed along containment above dam. Spontaneous sheen observed along containment boom at Ceresco Dam. Sheen and tar globules observed within containment at Ceresco Dam. Sheen within debris in Ceresco Dam containment. MP 15.5 RDB (South Mill Pond), no sheen observed. Boat-agitated sediment in north end of north Mill Pond (MP15.75), no sheen observed. Spontaneous sheen ribbons observed along boom C2 in Morrow Lake Delta. Crews removing debris from E4.0 control point in Morrow Lake Delta. North and south coves on Morrow Lake, no sheen observed. 		
	Additional observations: None		
1500	Return to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			